

Affected models and serial numbers	Inspection compliance times	Procedures
(5) AT-602, S/Ns 0662 through 0664.	Initially inspect upon the accumulation of 1,750 total hours TIS or within the next 100 hours TIS after the last inspection required by AD 2002-19-10, whichever occurs later. Repetitively inspect thereafter at intervals not to exceed 100 hours TIS until the upper and diagonal longerons are replaced and modified. Replacing and modifying the upper and diagonal longerons is the terminating action for the repetitive inspection requirement in this AD.	Inspect following Snow Engineering Co. Service Letter #213A, dated November 10, 2003, as specified in Snow Engineer Co. Service Letter #195, reissued November 10, 2003. Replace and modify following Snow Engineering Co. Service Letter #213B, revised November 10, 2003.
(6) AT-802 and AT-802A, S/Ns 0001 through 0004 and 0012 through 0118.	Initially inspect upon the accumulation of 250 total hours TIS or within the next 100 hours TIS after the last inspection required by AD 2002-19-10, whichever occurs later. Repetitively inspect thereafter at intervals not to exceed 100 hours TIS until the upper and diagonal longerons are replaced and modified. Replacing and modifying the upper and diagonal longerons is the terminating action for the repetitive inspection requirement in this AD.	Inspect following Snow Engineering Co. Service Letter #217A, dated November 10, 2003, as specified in Snow Engineer Co. Service Letter #195, reissued November 10, 2003. Replace and modify following Snow Engineering Co. Service Letter #217B, revised November 10, 2003.
(7) AT-802 and AT-802A, S/Ns 0005 through 0011.	Initially inspect upon the accumulation of 900	

¹ CAN-SPAM Act, section 3(2)(C). The term “the